

Troubleshooting Overview

This chapter provides information for troubleshooting automated DNA sequencing results from capillary electrophoresis runs.

Assumptions

Troubleshooting suggestions listed in this chapter assume the following:

- The instrument completed the run(s) and data are visible in Data Collection Software
- Sample files were extracted successfully
- The run folder was created and saved on the instrument computer
- The correct number of *.ab1 sample files were created within the run folder
- *.ab1 sample files can be opened and viewed in an Applied Biosystems analysis software program, such as Sequence Scanner or Sequencing Analysis Software

If these conditions are not met, you may have an instrument or Data Collection Software problem. You may need to repeat data extraction and/or data analysis. Refer to your instrument user guide to continue troubleshooting.

Using Controls

To simplify troubleshooting, Applied Biosystems recommends that you run controls with every run for multicapillary instruments or each set of runs on 310 instruments:

- **DNA template control (pGEM®-3Zf(+) or M13mp18)** ([page 64](#)) – Results can help you determine whether failed reactions are caused by poor template quality or sequencing reaction failure.
- **Sequencing standards** ([page 129](#)) – Results can help you distinguish between chemistry problems and instrument problems.

Troubleshooting Workflow

When troubleshooting, follow this workflow to identify the problem. In general, check for the errors that can be resolved most easily. The figures in this section show Sequencing Analysis Software examples, however you can use Sequence Scanner Software. For more information, see “[Analyzing Data with Sequencing Analysis Software](#)” on [page 170](#).

1. Review the electropherogram ([page 195](#)).
2. Review data analysis settings ([page 195](#)).
3. Review run and data analysis information ([page 196](#)).
4. Review experimental setup ([page 199](#)).
5. Note any patterns in the occurrence of the problem. For example, does the problem occur in specific capillaries, specific regions of the plate, an entire run, or multiple runs?
6. If you have not resolved your problem, identify the symptom in “[Table of Troubleshooting Symptoms](#)” on [page 201](#). Then, determine the cause and perform the actions to resolve the problem.
7. If the problem persists, contact Applied Biosystems Technical Support.

Reviewing the Electropherogram

1. Open the sample file in Sequencing Analysis Software and select the Electropherogram tab for the analyzed view. The analyzed view is rescaled. Then go to the raw view.
2. Review the current, voltage, temperature, and power throughout the electrophoresis run to determine whether an electrical problem occurred during the run. Large fluctuations in the values can result in poor quality data.

Note: Sequencing Analysis 5.X rescales the raw data to improve peak visibility in the Electropherogram view. Peak height in the Electropherogram view should not be used as the only indicator of data quality.







Figure 34 Example of electropherogram with high quality data

Reviewing Data Analysis Settings

Review data analysis settings using Sequencing Analysis Software.

1. In the Sample Manager, verify that the appropriate basecaller, mobility file (dyeset/primer), and matrix file (310 instruments only) are used:

Sample Manager													
Row	Show	Sample File Name	Sample Name	BC	PP	P	BaseCaller	DyeSet/Primer	Matrix File	Spacing	Peak 1	Start	Stop
1	<input type="checkbox"/>	 sample1	LRSv1.1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	KB.bcp	KB_3730_POP7_BDv1.mob	None	16.30	1872	1874	18760
2	<input type="checkbox"/>	 sample2	B17_07_ID030_122_Gv...	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Basecaller-3730POP7LR.bcp	DT3730POP7(BDv3).mob	None	15.06	2113	2113	18760
3	<input type="checkbox"/>	 sample3	Control_144	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Basecaller-3100RRv2.bcp	DT3100POP6(BDv3)v1.mob	None	11.13	2488	2488	14950

Verify that the mobility file (DyeSet/Primer) is appropriate for the basecaller

Bold, italic text indicates the file is not in the appropriate location

Matrix files are required for 310 instruments only

2. A change in nomenclature occurred between software versions. If the analysis file is in bold, italic text, verify that the analysis files are in the appropriate location:
 - **Basecaller file** – In the same folder as the Sequencing Analysis Software (for example: X:\Applied Biosystems\SeqA5.X\AppSeqA\bin\Basecaller\Params)
 - **Mobility file** – In the Mobility folder (for example: X:\Applied Biosystems\SeqA5.X\AppSeqA\bin\Basecaller\Mobility)
 - **Matrix file** – In the Matrix folder (for analysis of 310 instrument data) (for example: X:\Applied Biosystems\SeqA5.X\AppSeqA\bin\Basecaller\Matrix)

See Appendix C in the *Applied Biosystems DNA Sequencing Analysis Software User Guide* for more information on troubleshooting these files.

3. In the analysis protocol and settings, verify the basecaller settings.

Reviewing Run and Analysis Information

Review run and analysis information using Sequencing Analysis Software.

1. Click **Show** next to the sample you want to display.
2. Select the Raw tab and review the raw, unprocessed fluorescence data for the sample to assess the signal quality. Check for the following:
 - **Artifacts** – Are there any artifacts, such as four-color spikes? For an example of spikes, see [page 226](#).
 - **Peak heights** – Are peaks well-resolved, with reasonable heights ([Figure 35](#))? For examples of low or no signal, see [pages 207 through 211](#); for examples of top-heavy data, see [pages 222 through 225](#).
 - **Data start points** – Do any data start points deviate from others in the run? For examples of start point deviation, see [pages 213 and 214](#).
 - **Length of read** – Was the expected length of read obtained? Does the signal stop suddenly? For examples of sudden, premature drops in signal, see [pages 219 through 221](#).
 - **Baseline** – Is there background noise for all the peaks? Zoom in horizontally and vertically to verify the baseline noise.




Figure 35 Example of high quality raw data with tightly resolved peaks from the 3730 Genetic Analyzer

3. Select the Annotation tab and review the data collection and data analysis settings and values for the sample file ([Table 34](#)).

Table 34 Annotation tab information

Setting	Comments
Data Collection Settings	
Note: Incorrect Data Collection settings can result in basecalling errors during data analysis.	
Instrument Model	Make sure that the run parameters were appropriate for the instrument model (for more information, see page 151).
Length to Detector	Capillary length. If the incorrect length was set, peaks can begin later than expected (for an example, see page 213). Note: For 310 instruments, the length to detector value does not affect data analysis.
Run Module Name	If the incorrect run module was used, peaks can begin later than expected (for an example, see page 213) or basecalling may be affected.
Data Analysis Settings	
Basecaller Name	For more information about the basecallers, see page 144 .
DyeSet/Primer or Mobility File	If the incorrect mobility file was applied in the analysis, peaks are not evenly spaced, especially peaks in the first 100 to 150 bases (for an example, see page 229) and/or base assignments may be incorrect.
Ave Signal Intensity	Low or high values can produce low quality data (for examples, see pages 231, 233, page 239 , and page 242). Generally acceptable values: <ul style="list-style-type: none"> • 3730/3730xl instruments: 500 to 10,000 rfus • 310 and 31XX instruments: 50 to 1000 rfus Note: The values listed above are not specifications.
Signal:Noise	Average relative fluorescent units (rfu) divided by the noise level for each dye. High quality data normally yields a signal to noise ratio >100, although accurate basecalling can be achieved with values as low as 25.
Base Spacing Used	A negative number indicates abnormal peak spacing values. Basecalling may not be accurate for the sample.

4. Select the EPT tab and review the current, voltage, temperature, and power throughout the electrophoresis run to determine whether a gross electrical problem occurred during the run. Large fluctuations in the values can result in poor quality data.




Figure 8-36 Example of EPT tab information for high quality data

Reviewing Experimental Setup

1. Confirm that you used the optimal quality and quantity of DNA using [Table 35](#).

Table 35 Reviewing DNA quality and quantity checklist

✓	Recommendation	Comments
	Run an agarose gel to detect any contaminating DNA or RNA.	<p>Purified DNA runs as a single band on an agarose gel.</p> <p>Note: Uncut plasmid DNA can run as three bands: supercoiled, nicked, and linear.</p> <p>Note: RNA contamination up to 1 µg can be tolerated in the sequencing reaction, but it affects DNA quantitation greatly.</p>
	Measure the A_{260}/A_{280} ratio of your samples.	<p>For pure preparations of DNA (in TE), the A_{260}/A_{280} ratio is 1.8. For pure preparations of RNA (in TE), the ratio is 2.0. Very clean samples in pure water can give a ratio of 1.5 to 1.6. (Sambrook <i>et al.</i>, 1989)</p> <p>Smaller ratios may indicate the presence of protein or organic contaminants. Ratios less than 1.8 may still produce high quality results.</p>
	Quantitate the DNA template using the absorbance at 260 nm (A_{260}).	Quantitation by agarose gel electrophoresis may not be accurate because ethidium bromide incorporation is not consistent and the method of comparing the standard and sample brightness is subjective.
	Dilute or concentrate the DNA as needed to obtain an A_{260} reading between 0.05 and 1.00.	A_{260} values below 0.05 or above 1.00 are not accurate because Beer's law generally applies only within a certain concentration range. Outside of this concentration range, the relationship between absorbance and concentration is nonlinear.
	<p>Use the amount of DNA template in Table 8, "Recommended DNA template quantities for cycle sequencing," on page 63.</p> <p>Calculate the template concentration using the formulas on page 45.</p>	<p>Too little template can result in no or low signal.</p> <p>Too much template can result in top heavy data (page 222 through 225).</p>
	<p>Use the primer concentrations recommended in Chapter 4: 3.2 pmol in a 20-µL reaction (dye terminator chemistry).</p> <p>Calculate the primer concentrations using the formula on page 39.</p>	<p>Too little primer can result in no or low signal (pages 207 through 211).</p> <p>Too much primer can lead to overamplification of the 5' end of the template, resulting in top heavy data (page 222 and 224).</p>

2. Confirm that the primer design and quality are optimal using [Table 36](#).

Table 36 Reviewing primer design checklist

✓	Recommendation	Comments
	Ensure that the primer has $T_m > 45$ °C.	If the T_m is too low, it may result in poor priming and low or no signal (pages 207 through pages 211).
	Ensure that primers are at least 18 bases long.	Primers that are too short may have T_m s that are too low.
	Ensure that there are no known secondary hybridization sites on the target DNA.	Secondary hybridization sites on the target DNA can result in double peaks throughout the sequence (page 237).
	Choose primers that do not have runs of identical nucleotides, especially 4 or more Gs.	Runs of identical nucleotides in primers can cause n+1 or n-1 effects (page 244). Also, these primers may be more difficult to synthesize.
	Choose primers with G-C content in the range of 30 to 80%, preferably 50 to 55%.	If the G-C content is too low, the T_m may be too low. If so, increase the primer length beyond 18 bases to obtain a $T_m > 45$ °C.
	Design primers to minimize the potential for secondary structure and/or hybridization (see page 38).	Primer-dimer formation from hybridization can result in mixed sequence at the beginning of the sequence (page 240). Secondary structure in the primer, particularly at the 3' end can result in poor priming and low or no signal (pages 207 through pages 211).
	Purify primers by HPLC to reduce the quantity of n-1 primers.	Primers containing contaminants or synthesized primers of the wrong length can cause problems in sequencing reactions, such as failed reactions, noisy data, or poor sequencing results. If the primer is a short oligo that contains n-1 primers, HPLC cannot always remove the n-1 contaminants.

Table of Troubleshooting Symptoms

The table below lists troubleshooting symptoms and a page reference for an example of the symptom and possible causes and actions to take to resolve the problem. If there are two or more possible causes for the symptom, the causes are grouped and listed in the following order: data analysis issues, electrophoresis issues, then sequencing reaction issues.

Table 37 Table of troubleshooting symptoms

Symptom	Example on Page
Sample Manager Errors	
Spacing value is red in Sequence Analysis or Sequence Scanner Software	203
Incorrect Basecalling	
Mixed base not called correctly	204
Too many mixed bases called	205
Irregular Signal	
No signal or low signal: <ul style="list-style-type: none"> No signal Low signal Low signal throughout 	207 209 211
Signal starts later than expected: <ul style="list-style-type: none"> Signal starts later than expected: no resolution loss Signal starts later than expected: with resolution loss 	213 214
Irregular baseline: <ul style="list-style-type: none"> Negative baseline: one color Negative baseline: all four bases Waterfall baseline 	216 217 218
Sudden drop in signal: <ul style="list-style-type: none"> Sudden drop in signal: corresponds to basecalling stop when sequencing short template Sudden drop in signal: early sudden drop with sequence termination Sudden drop in signal: sudden drop with continued basecalling 	219 220 221
Top-heavy data: <ul style="list-style-type: none"> Top-heavy data: gradual loss of signal Top-heavy data: ski slope profile Top-heavy data: preferential amplification of short sequence Top-heavy data: split peaks with excessive signal 	222 223 224 225

Table 37 Table of troubleshooting symptoms (*continued*)

Symptom	Example on Page
Abnormal Peak Shapes	
Spikes:	
• Four-color spikes	226
• One-color spikes	227
• Large spike at the end of the run	228
Improperly spaced peaks, especially peaks in the first 100 to 150 bases	229
Large peaks (blobs) in the first 120 bases	230
Irregular C peaks using BigDye® Terminators v3.1	231
Irregular G peaks using BigDye® Terminators v1.1 and 3.1	233
Shoulders on all peaks	234
Peak compressions	235
Broad peaks for bisulfite-converted sequences	236
Double peaks:	
• Double peaks: peaks under peaks throughout	237
• Double peaks: with high average signal intensity values	239
• Double peaks: at the beginning of the sequence	240
• Double peaks: at the beginning of the sequence (bisulfite conversion)	241
• Double peaks: specific peaks under specific bases	242
• Double peaks: specific peaks under specific bases	243
• Double peaks: peaks under peaks throughout (bisulfite conversion)	244
• Double peaks: after a homopolymer or repeated sequence	246
• Double peaks: after a homopolymer or repeated sequence (bisulfite sequencing)	247
• Double peaks: double sequence after clean sequence	248
Low Resolution	
Resolution loss: at beginning of run	249
Resolution loss: in the middle of the run	250
Resolution loss: gradual early loss	251
SeqScape Software Symptoms	
High quality sequence in unassembled category in SeqScape Software	253

Troubleshooting Examples


Spacing value is red in Sequence Analysis or Sequence Scanner Software

Row	Show	Sample File Name	Sample Name	BC	PP	P	BaseCaller	DyeSet/Primer	Matrix File	Spacing	Peak 1	Start	Stop
1		BD17946_P21_m9	6463				KB.bcp	KB_3730_POP7_B...	None	16.16	2798	2799	18436

Red spacing value in
Sample Manager

Possible Cause(s)	Recommended Action
Data analysis issue: The red color indicates that the basecaller applied a default value for spacing. The basecaller determined that the sample cannot be analyzed because the spacing estimation algorithm failed. This error may occur if the data has been collected using modified run modules or if data are poor.	Verify that analysis settings are appropriate for the run setup. Manually set a spacing value and reanalyze the data. To estimate a spacing value: <ol style="list-style-type: none"> 1. Refer to the raw data after 1000 scan points. 2. Measure the distance between the crests of two adjacent peaks with the same color. For more information, see the appropriate Sequencing Analysis Software user guide.

Mixed base not called correctly




Ns or low QVs for pure bases are assigned instead of mixed bases (analysis using the KB basecaller only)

Electropherogram

Possible Cause(s)	Recommended Action
Data analysis issue: The quality threshold setting and the mixed bases settings are not correctly defined in the analysis protocol.	<ol style="list-style-type: none"> 1. Review the quality threshold setting (page 149) and the mixed bases settings (page 149) in the analysis protocol that you used for the analysis. 2. Correct the settings if necessary, then reanalyze the data. <p>Note: Significant improvements in mixed basecalling have been made with later versions of Sequencing Analysis Software and the KB basecaller. Please check the Applied Biosystems web site for the latest updates.</p>

Too many mixed bases called




Too many mixed bases are called (analysis using the KB basecaller only)

Possible Cause(s)	Recommended Action
Data analysis issues:	
2nd highest peak threshold for mixed base identification is set too low. The recommended range is 15 to 25%.	Review the Mixed Bases settings in the analysis protocol that you used for the analysis (page 149). Change the settings if necessary, then reanalyze.
Electrophoresis issues (likely in multiple lanes and/or runs):	
Carryover from contaminated septa.	Replace septas and change buffer, water, and waste.
Electrical noise.	Check the uninterruptible power supply (UPS).
Contaminated water or buffer because of dirty containers, microbial growth, or use of tap water for cleaning.	Clean all reservoirs, upper and lower polymer block, and septa with deionized water.
Poor or incorrect spectral calibration (spectral pullup).	Perform the spectral calibration again.
Shifted spatial calibration.	Perform the spatial calibration again.
Poor CCD alignment.	Contact Applied Biosystems to arrange a service engineer visit.
Sequencing reaction issues (in individual samples or multiple samples):	
Secondary primer site in the template was sequenced.	Design a new sequencing primer (page 38).
Secondary amplification product in the PCR product used as a sequencing template.	Use gel purification to isolate the desired product. For more information, see “ Purifying PCR Products for Sequencing ” on page 41 .
	Design new PCR primers or optimize amplification parameters to obtain a single product. For more information, see “ Preparing PCR DNA Templates ” on page 37 .
PCR primers were not completely removed from the PCR product used as a sequencing template.	Remove PCR primers completely before using PCR products as sequencing templates. For more information, see “ Purifying PCR Products for Sequencing ” on page 41 .
Mixed templates.	Review the DNA quality.

Possible Cause(s)	Recommended Action
Pull-up caused by overloading the capillaries with too much product.	Review DNA quantity.
	Use standard run modules
	<p>Click the Annotation tab and examine the Ave Signal Intensity. Excessive signal:</p> <ul style="list-style-type: none"> 3730/3730xl instruments: >10,000 rfus 310 and 31XX instruments: >1000 rfus <p>Load less labeled sample by performing one of the following:</p> <ul style="list-style-type: none"> Remove some of the sample and replace with Hi-Di™ Formamide Inject sample for less time Resequence the samples, using less template in the sequencing reaction, especially if you use the BigDye® XTerminator™ Purification Kit (see Table 8, “Recommended DNA template quantities for cycle sequencing,” on page 63).
<p>Stutter during either PCR amplification and/or cycle sequencing. Stutter is most common in any homopolymeric region greater than 2 bases. It can also be seen with simple repeated DNA sequences. The results are worse when the stutter occurs during PCR amplification.</p> <p>It is thought that stutter occurs when a partially extended primer and template dissociate, then reanneal improperly before extension continues. Partially extended primers and templates commonly dissociate during the reaction, but if they reanneal with complete fidelity, the reaction produces only one product. Improper annealing results in one or more products that are represented in the sequencing results.</p>	<p>If stutter occurs during PCR amplification, little can be done to correct the problem, except using anchored sequencing primers.</p> <p>If stutter occurs during cycle sequencing:</p> <ul style="list-style-type: none"> Try using dRhodamine terminators. They have been shown to be less prone to produce stutters, specifically with poly-T regions. Some customers have found that they can get past poly(A) regions using a mixture of oligo dT₁₈ primers with either a C, A, or G as the 3' terminal dinucleotide or 2-base anchors.


No signal



Possible Cause(s)	Recommended Action
Sequencing reaction issues (likely with multiple or all samples):	
Loss of labeled product during purification of extension products.	See Chapter 5 for suggestions on retaining labeled product during purification.
Thermal cycler malfunction.	Determine with the manufacturer how to test your thermal cycler for proper performance.
One of the components of the sequencing reaction (template, primer, or Ready Reaction Mix) was either omitted, was the wrong material, or was of poor quality.	Review the entire experiment carefully. <ol style="list-style-type: none"> 1. Check the quantitation and quality of the sequencing reaction components. 2. For each component, replace the component, perform a sequencing run, then evaluate the results until you have identified the problem or replaced all of the reaction components. 3. Run a DNA template control to determine whether the sequencing reaction failed or the template quality is low (page 64).
Insufficient template added to sequencing reactions, leading to too few sequencing products generated during PCR.	Check DNA quantitation and quality (page 44 and 45).
Template contains sequencing inhibitors such as phenol (page 44).	Follow recommended procedures to prepare templates. Check DNA quality (page 44). If necessary, clean up dirty templates.

Possible Cause(s)	Recommended Action
No enzyme activity because Ready Reaction Mix was stored improperly or it separated upon storage.	Check the color of the Ready Reaction Mix. If the color is not uniform, the Ready Reaction Mix separated upon storage. Mix the Ready Reaction Mix gently before using it.
	Run a DNA template control to test enzyme function (page 64).
Weak priming because of poor primer design.	Review primer design (page 38). Make new primers, then repeat the sequencing experiment.

Low signal




Electropherogram shows
Ns (with ABI or KB
basecaller) or low quality
bases (with KB basecaller)

Possible Cause(s)	Recommended Action
Electrophoresis issues:	
One or more broken or blocked capillaries.	Visually check the capillaries. If any are broken or blocked, replace the entire array. If subsequent runs show failure in the same capillary, replace the entire array.
	Check the results using the long read sequencing standard.
Optical path is obstructed (3100/3100- <i>Avant</i> instruments only).	Check the laser power, using the EPT in Data Collection Software. Perform the spatial calibration again.
	Check whether you can hear the shutter clicking during data collection. If you cannot hear it click, contact Applied Biosystems for a service engineer visit.
	If all capillaries show no signal or low signal, contact Applied Biosystems for a service engineer visit.

Possible Cause(s)	Recommended Action
Sample evaporated because water was used as the injection solution.	Use Hi-Di™ Formamide to resuspend your samples (see page 122). For future experiments, consider using the BigDye® XTerminator™ Purification Kit to purify samples (see page 88).
	Use a heat sealer to seal the plates (3730/3730x/ instruments only).
	Add more resuspension solution to the samples before loading them.
Sample volume is too low.	Resuspend samples using sufficient volumes (at least 10 µL) (see page 122).
Autosampler alignment is off and the tips did not enter the sample.	<ol style="list-style-type: none"> 1. Verify the correct run module was used. 2. If you are using samples purified with BigDye® XTerminator™ Purification Kit and your autosampler was recently calibrated, run the BDX Update utility. Select Start ▶ All Programs ▶ Applied Biosystems ▶ BDX Updater. (The utility is installed with the BigDye XTerminator run modules.) 3. Contact Applied Biosystems to arrange a service engineer visit.
Slightly unstable current and voltage during electrophoresis.	Check the current and voltage.
Buffer is old.	Replace the buffer according to the procedures in your instrument user guide.
Too much template or sample temporarily clogging the capillary.	Reinject the sample.
Injection failed.	<ul style="list-style-type: none"> • Verify correct run module was used. • Verify correct volume in well. • Verify capillaries are not broken or blocked.


Low signal throughout



Possible Cause(s)	Recommended Action
Sequencing reaction issues:	
Sequencing reaction failed.	Check the control template and primer.
Partial loss of labeled products during purification of extension products.	See Chapter 5 for suggestions on retaining labeled product during purification.
Sample contains salts from insufficient purification of templates, PCR products, or sequencing reactions with ethanol precipitation. Salts in the sample interfere with proper electrokinetic injection.	Review DNA quality, PCR purification, and sequencing reaction purification steps.
The amount of Ready Reaction Mix in the reactions was insufficient, usually because the sequencing chemistry was diluted.	Follow recommended procedures to prepare sequencing reactions with Ready Reaction Mixes. See page 66 for recommended procedures. Applied Biosystems does not support diluted reactions or guarantee the performance of diluted BigDye chemistry.
Not enough primer or template in the cycle sequencing reaction.	Review DNA quantity (page 199). Use the amounts recommended on page 63 . Run a DNA template control to check sequencing reaction quality (page 64).


Possible Cause(s)	Recommended Action
Poor template quality.	Follow recommended procedures to prepare templates. Check DNA quality (page 44). If necessary, clean up dirty templates. Run a DNA template control to check sequencing reaction quality (page 64).
Failure caused by difficult template sequence.	Use Table 7 on page 56 to select a chemistry kit for certain difficult templates.

Signal starts later than expected: no resolution loss



Possible Cause(s)	Recommended Action
Electrophoresis issues:	
Incorrect capillary length (Length to Detector) or run module was selected.	<ol style="list-style-type: none"> Review run information in the Annotation tab using Sequencing Analysis Software (see page 197): <ul style="list-style-type: none"> Length to Detector Run module If an incorrect selection was made, run the samples again using the correct settings.
Variation in lab temperature leads to faster or slower runs.	Stabilize the lab temperature.
Sample heated during vortexing step of BigDye® XTerminator™ purification.	<ol style="list-style-type: none"> Repeat the sequencing reactions. Perform BigDye XTerminator purification using recommended vortexer and plate adapter. Run the samples again.
Too much template used.	Run the samples again, using less template.


Signal starts later than expected: with resolution loss




Possible Cause(s)	Recommended Action
Electrophoresis issues:	
Capillaries overloaded with sequencing product, possibly unlabeled DNA or RNA.	Click the Annotation tab and examine the Ave Signal Intensity. Excessive signal: <ul style="list-style-type: none"> 3730/3730xl instruments: >10,000 rfus 310 and 31XX instruments: >1000 rfus Re-inject the samples using decreased injection time and/or lower voltage. Load less labeled sample by using less template in the sequencing reaction (see Table 8, "Recommended DNA template quantities for cycle sequencing," on page 63).
Temperature in room and/or oven fluctuating.	Review the EPT tab using Sequencing Analysis Software (see page 198). If the oven temperature is fluctuating, the oven may be leaking because of a poor seal. Contact Applied Biosystems to arrange a service engineer visit.
Contaminant migrated through the capillary during electrophoresis.	Run the sample again.
Capillary not filling.	Check the pin valve in the polymer block, amount of polymer in the bottle, leaks in the check valves, and polymer pump function. Contact Applied Biosystems to arrange a service engineer visit.
Temperature in the array heater fluctuating more than $\pm 0.5^{\circ}\text{C}$ (3730/3730xl and 3130/3130xl instruments and POP-7 only).	Using Data Collection Software, check the array heater temperature. If it fluctuates more than $\pm 0.5^{\circ}\text{C}$, contact Applied Biosystems to arrange a service engineer visit.

Possible Cause(s)	Recommended Action
Water in polymer system caused by insufficient flushing after water wash maintenance.	Flush the polymer, using the wizard if possible.
Extension products purified using bead-based kits were injected without removing the magnetic beads. The beads may interfere with the extension products during injection and cause overloading or other injection anomalies.	Remove magnetic beads before loading the sample.
Variables that affect current set incorrectly.	<ul style="list-style-type: none">• Replace buffer in system with fresh 1X running buffer.• Inspect system for leaks (wet or dry polymer around fitting indicates a leak) and tighten fittings as needed.• Look for discoloration in the block channels or tubing. If present, perform a water wash on the system using the wizard in Data Collection Software.

Negative baseline: one color




Baseline fluorescence for one color is below 0 rfus



Software corrects the baseline fluorescence during data analysis


Possible Cause(s)	Recommended Action
You are using an early version of Sequencing Analysis Software. This error, found in versions earlier than v5.2, was corrected in Basecaller updater v2.0.	Upgrade Sequencing Analysis Software v5.2 or later. To obtain the latest software updates and patches, go to www.appliedbiosystems.com , then click the link for Support.

Negative baseline: all four bases




Possible Cause(s)	Recommended Action
Electrophoresis issue: Excessive fluorescent contamination in the detection area that bleaches out over the duration of the run (3730/3730x/ instruments only).	Use manual control to turn on the laser before starting the run to negate the effects of excessive fluorescent contaminant. Contact Applied Biosystems technical support or a field applications specialist.
	Perform a water wash on all components of the system using the wizard in Data Collection Software, then replace the capillary array.

Waterfall baseline




Possible Cause(s)	Recommended Action
Residue from cleansers used on glassware. Note: Primarily observed in syringe-based instruments.	Rinse all components with deionized water. Check gasket on syringe(s), replace if necessary. Replace syringe(s).

Sudden drop in signal: corresponds to basecalling stop when sequencing short template




Possible Cause(s)	Recommended Action
Data analysis issue: The drop in signal identifies a PCR stop point and the basecaller stops calling bases beyond this point. With the ABI basecaller, you observe Ns beyond the PCR stop. With the KB basecaller, the analyzed trace is displayed until the last basecall.	Select the At PCR Stop check box in the analysis protocol using Sequencing Analysis Software (see page 148).

Sudden drop in signal: early sudden drop with sequence termination




Possible Cause(s)	Recommended Action
Sequencing reaction issue:	
DNA polymerase enzyme stopped at a region of the template that was difficult to sequence.	<ul style="list-style-type: none"> Depending on sequence contexts, you can try sequencing some template with dGTP kits (if the problem sequence is G-rich), dRhodamine kits, or BigDye primer kits. If termination of sequencing was caused by hairpins or secondary structure, redesign primers around the problem region. Some customers report that certain additives can help, but Applied Biosystems cannot recommend any specific protocols.
Not enough Ready Reaction Mix was used in the sequencing reaction.	Follow recommended procedures to prepare sequencing reactions with Ready Reaction Mixes. See page 66 for recommended procedures. Applied Biosystems does not support diluted reactions or guarantee the performance of diluted BigDye chemistry.

Sudden drop in signal: sudden drop with continued basecalling




Possible Cause(s)	Recommended Action
Sequencing reaction issues:	
DNA polymerase had difficulty processing through a particular sequence context.	Depending on sequence contexts, you can try sequencing some template with dGTP kits, dRhodamine kits, or BigDye® primer kits.
Not enough Ready Reaction Mix was used in the sequencing reaction.	Follow recommended procedures to prepare sequencing reactions with Ready Reaction Mixes. See page 66 for recommended procedures. Applied Biosystems does not support diluted reactions or guarantee the performance of diluted BigDye chemistry. If the problem persists, try sequencing using the dGTP kits.

Top-heavy data: gradual loss of signal



Possible Cause(s)	Recommended Action
Sequencing reaction issues:	
Improper cycling conditions for extension. The extension time is too short or the extension temperature is too high.	Increase the extension time or decrease the extension temperature.
Improper ratio of primer to template in the sequencing reaction.	Set up a matrix of reactions with varying ratios of primer:template to determine which ratio produces the best peak profile.
Sequencing template contains a contaminant that inhibits DNA polymerase activity.	Review how templates are prepared. Try a different method or clean up dirty templates (page 44).
Not enough Ready Reaction Mix was used in the sequencing reaction.	Follow recommended procedures to prepare sequencing reactions with Ready Reaction Mixes. See page 66 for recommended procedures. Applied Biosystems does not support diluted reactions or guarantee the performance of diluted BigDye chemistry.
Template or extension products are degraded. With degraded extension products, the data are noisy, with a higher baseline at the start of peaks.	Review how templates are prepared and stored. Try a different method (Chapter 3) and store at -20°C .


Top-heavy data: ski slope profile



Peak profile is similar to a ski slope: peak heights decrease as the fragment lengths increase

Possible Cause(s)	Recommended Action
Sequencing reaction issues:	
Not enough or too much template was used in the sequencing reaction.	Review the DNA quantity (page 199).
Not enough or too much primer was used in the sequencing reaction.	
Not enough Ready Reaction Mix was used in the sequencing reaction.	Follow recommended procedures to prepare sequencing reactions with Ready Reaction Mixes. See page 66 for recommended procedures. Applied Biosystems does not support diluted reactions or guarantee the performance of diluted BigDye chemistry.
Template is degraded.	Review how templates are prepared and stored. Try a different method (Chapter 3) and store at – 20 °C.


Top-heavy data: preferential amplification of short sequence



Short 5' sequence, instead of the entire template, is amplified preferentially, (see also [page 240](#))


Possible Cause(s)	Recommended Action
Sequencing reaction issue: Primer-dimer formation during the PCR reaction.	Redesign the PCR primers to eliminate the sequences that allow primer-dimer formation.
	Use a “hot start” PCR enzyme to inhibit primer-dimer formation.

Top-heavy data: split peaks with excessive signal




Possible Cause(s)	Recommended Action
Sequencing reaction issues:	
Signal is too high because too much template was used in the sequencing reaction and too much sequencing product was created.	<p>You do not have to repeat the reaction.</p> <p>Click the Annotation tab and check the Ave Signal Intensity. Excessive signal:</p> <ul style="list-style-type: none"> 3730/3730xl instruments: >10,000 rfus 310 and 31XX instruments: >1000 rfus <p>Especially if your samples were purified using the BigDye® XTerminator™ Purification Kit, load less labeled sample by performing one of the following:</p> <ul style="list-style-type: none"> Remove some of the sample and replace with Hi-Di™ Formamide Inject sample for less time Resequence the samples, using less template in the sequencing reaction, especially if you use the BigDye® XTerminator™ Purification Kit (see Table 8, “Recommended DNA template quantities for cycle sequencing,” on page 63). <p>For future reactions, reduce the amount of template in the sequencing reaction.</p>
Injection height incorrect due to incorrect run module.	Use correct run module, especially for samples purified with the BigDye XTerminator Purification Kit (see “Selecting a Run Module” on page 137).

Four-color spikes




Possible Cause(s)	Recommended Action
Electrophoresis issues:	
Dust, bubbles, or crystals in polymer passed through the path of the laser beam.	<div>1. Eliminate large amounts of dust in the environment.</div> <div>2. Inspect the upper gel block for bubbles. If present, flush all bubbles out of the system and out of the array manually.</div> <div>3. Check the polymer bottle for crystals. If present, warm the polymer gently to 30 °C with gentle mixing, then refill the syringes and array with the polymer.</div> <div>4. Replace polymer if the condition persists.</div>
Polymer is expired or was stored at room temperature for more than 7 days.	Replace the polymer.

One-color spikes




Possible Cause(s)	Recommended Action
Electrical noise or power fluctuations.	Verify the power source, use uninterruptible power supply.
Polymer temperature is too high.	<ul style="list-style-type: none"> • Verify the shipping temperature of the polymer. • Verify lab temperature is below 26 °C.
Well volume is too low.	<ul style="list-style-type: none"> • Verify volume is $\geq 10\mu\text{L}$ for 96-well plates and $\geq 15\mu\text{L}$ for 384-well plates. • If using septa, verify septa are fresh to minimize evaporation.

Large spike at the end of the run



Possible Cause(s)	Recommended Action
The large spike at the end of the run, called a reptation peak, occurs with almost all electrophoretic separations of DNA on capillary instruments. With typical run conditions, data collection stops well before the spike occurs. There is no useful sequencing information in the spike or just before the spike. Because some run modules are designed for the longest possible read lengths, data collection stops just before the spike occurs. Normal run variation within a lab may result in the spike appearing in some electropherograms.	None needed. Shorten the data collection time a few minutes to remove a persistent spike from your data.


Improperly spaced peaks, especially peaks in the first 100 to 150 bases



Peaks are improperly spaced, especially peaks in the first 100 to 150 bases


Possible Cause(s)	Recommended Action
Data analysis issue: Wrong mobility file applied to the sequence data.	Reanalyze the data using the correct mobility file to observe proper spacing of all peaks. For more information about mobility files, see page 145 .

Large peaks (blobs) in the first 120 bases




Blobs in the first 120 bases
Precise location of the blobs
varies according to the dye
used and the specific
configuration

Possible Cause(s)	Recommended Action
Sequencing reaction issues:	
Incomplete removal of dye-labeled terminators after the cycle sequencing reaction.	Review the methods described in Chapter 5, "Purification of Extension Products." If you are using a third-party product for purifying extension products, contact the manufacturer for troubleshooting help. For future experiments, consider using the BigDye® XTerminator™ Purification Kit to purify samples (see page 88).
Poor incorporation of terminators, leaving excess unincorporated terminators.	Review the entire experiment carefully. <ul style="list-style-type: none"> • Check the quantitation (page 45). • Check the quality of the sequencing components. Replace each component, one at a time. • Run a DNA template control to determine whether the sequencing reaction failed or the template quality is low (page 64). • Check expiration dates on all reagents and replace any that have expired.
If using BigDye XTerminator Purification Kit, insufficient mixing during vortexing step.	<ul style="list-style-type: none"> • Verify plate is firmly attached to vortexer. • Follow protocol for vortexing.
If using BigDye XTerminator Purification Kit, incorrect ratio of BigDye XTerminator reagents.	<ul style="list-style-type: none"> • Vortex the XTerminator Solution bulk container at maximum speed for at least 10 seconds before dispensing. • Use wide-bore pipette tips to dispense the XTerminator Solution.




Possible Cause(s)	Recommended Action
Electrophoresis issue:	
The buffer heater is powered on (3730/3730x/ instruments only).	Verify that the buffer heater is not powered on.
Severe arcing events can mask the C signal.	<ul style="list-style-type: none">• Perform several water washes using the wizard in Data Collection Software.• Disassemble the system and clean out all components with warm water (<42 °C).

Irregular G peaks using BigDye® Terminators v1.1 and 3.1




Possible Cause(s)	Recommended Action
Electrophoresis issue: The buffer heater is powered on (3730/3730x/ instruments only).	If you are using the 3730 instrument, confirm that the buffer heater is not powered on.
Sequencing reaction issues:	
The Hi-Di™ Formamide is degraded.	Resuspend the samples using a newer lot of Hi-Di Formamide.
Sequencing reactions were exposed to light, heat, acidic conditions, and/or oxygen before they were loaded onto the instrument.	Use tube septa or a heat seal to prevent exposure to air and evaporation of samples, especially if you place the samples in the autosampler more than 6 hours before starting electrophoresis.
	Verify that the primer pH and the template pH are not acidic.
The dye labels attached to the ddG terminators are degraded. As shown in the figure above, the pattern for degradation of dye labels on ddG terminators is different than for ddC terminators. The G peak patterns are very irregular, and the complexity increases as degradation progresses. This problem can occur with BigDye Terminators v1.1 and less frequently with BigDye Terminators v3.1.	Protect the fluorescently labeled DNA from light, heat, acidic conditions, and oxygen (see “Storing Sequencing Reactions” on page 121).
Water used as Injection solution. Note: Resuspending samples in water leads to breakdown of C and/or G-labeled fragments.	Degradation of the dye labels attached to the ddG terminators is less likely to occur in Hi-Di Formamide or 0.1 mM EDTA.

Shoulders on all peaks




Possible Cause(s)	Recommended Action
Electrophoresis issues:	
Capillary array needs to be replaced.	Replace the capillary array.
Overloaded sample.	Shorten the injection time.
	Amplify less DNA.
Sequencing reaction issues:	
Contamination of the sequencing primer with n+1 or n-1 sequencing primer.	Use the primers with a different template. If the problem persists, resynthesize the primers before repeating the experiment.
<p>Stutter during either PCR amplification and/or cycle sequencing. Stutter is most common in any homopolymeric region greater than 2 bases. It can also be seen with simple repeated DNA sequences. The results are worse when the stutter occurs during PCR amplification.</p> <p>It is thought that stutter occurs when a partially extended primer and template dissociate, then reanneal improperly before extension continues. Partially extended primers and templates commonly dissociate during the reaction, but if they reanneal with complete fidelity, the reaction produces only one product. Improper annealing results in one or more products that are represented in the sequencing results.</p>	<p>If stutter occurs during PCR amplification, little can be done to correct the problem, except using anchored sequencing primers.</p> <p>If stutter occurs during cycle sequencing:</p> <ul style="list-style-type: none"> Try using dRhodamine terminators. They have been shown to be less prone to produce stutters, specifically with poly-T regions. Some customers have found that they can get past poly(A) regions using a mixture of oligo dT₁₈ primers with either a C, A, or G as the 3' terminal dinucleotide or 2-base anchors.
Blending Ready Reaction Mixes from dGTP BigDye terminator kits with BigDye terminator vx.1 kits.	Do not use blended Ready Reaction Mixes of dGTP BigDye terminator kits and BigDye Terminator vx.1 kits.


Peak compressions



Possible Cause(s)	Recommended Action
Sequencing reaction issue: Observed when sequencing GC-rich regions using dGTP sequencing chemistry. Thought to result from incomplete denaturation of the synthesized DNA.	No corrective action is known at this time. Some customers report that using BigDye primers corrects this problem.




Double peaks: peaks under peaks throughout



Possible Cause(s)	Recommended Action
Electrophoresis issues:	
Carryover from contaminated septa.	Replace septas, then change buffer, water, and waste.
Electrical noise.	Check the uninterruptible power supply (UPS).
Dirty containers and/or tap water were used to clean instrument components, resulting in contaminated water or buffer.	Clean the containers to be used for cleaning instrument components, then rinse the containers thoroughly with deionized water. It is preferable to use deionized water to clean the instrument components.
Shifted spatial calibration.	Redo the spatial calibration.
Poor CCD alignment.	Contact Applied Biosystems to arrange a service engineer visit.
Poor or incorrect spectral calibration (spectral pull-up).	Redo the spectral calibration.
Sequencing reaction issues:	
Secondary primer site in the template was sequenced.	Design a new sequencing primer (page 38).
Secondary amplification product in the PCR product used as a sequencing template.	Use gel purification to isolate the desired product or design new PCR primers to obtain a single product. For more information, see “Preparing PCR DNA Templates” on page 37 .
PCR primers were not completely removed from the PCR product used as a sequencing template.	Remove PCR primers completely before using PCR products as sequencing templates. For more information, see “Preparing PCR DNA Templates” on page 37 .
Mixed or contaminated templates or primers.	Review the DNA quality.

Possible Cause(s)	Recommended Action
<p>Stutter during either PCR amplification and/or cycle sequencing. Stutter is most common in any homopolymeric region greater than 2 bases. It can also be seen with simple repeated DNA sequences. The results are worse when the stutter occurs during PCR amplification.</p> <p>It is thought that stutter occurs when a partially extended primer and template dissociate, then reanneal improperly before extension continues. Partially extended primers and templates commonly dissociate during the reaction, but if they reanneal with complete fidelity, the reaction produces only one product. Improper annealing results in one or more products that are represented in the sequencing results.</p>	<p>If stutter occurs during PCR amplification, little can be done to correct the problem, except using anchored sequencing primers.</p> <p>If stutter occurs during cycle sequencing:</p> <ul style="list-style-type: none">• Try using dRhodamine terminators. They have been shown to be less prone to produce stutters, specifically with poly-T regions.• Some customers have found that they can get past poly(A) regions using a mixture of oligo dT₁₈ primers with either a C, A, or G as the 3' terminal dinucleotide or 2-base anchors.
Very strong or offscale data	<p>Reduce the signal:</p> <ul style="list-style-type: none">• Adjust the injection time and/or lower the voltage• Reduce the template concentration or use less sample


Double peaks: with high average signal intensity values



Number of Bases Detected:	565	Annotation
Sample Score (from whole sequence):	21	
Base Call Start (Scan #):	2117	
Base Call End (Scan #):	14593	
Peak 1 Location (Scan #):	2117	
Ave Signal Intensity:	G (3062), A (4426), T (4530), C (3217)	Ave Signal Intensity values are too high for data from a 3100 instrument
Noise:	G (4), A (6), T (6), C (5)	
Signal:Noise:	G (714), A (798), T (817), C (704)	

Possible Cause(s)	Recommended Action
Sequencing reaction issue: Signal is too high for data from the instrument. See page 197 for valid ranges.	Click the Annotation tab and examine the Ave Signal Intensity. Excessive signal: <ul style="list-style-type: none"> 3730/3730xl instruments: >10,000 rfus 310 and 31XX instruments: >1000 rfus Load less labeled sample by performing one of the following: <ul style="list-style-type: none"> Dilute the resuspended product with Hi-Di™ Formamide before loading onto the instrument Inject sample for less time Resequence the samples, using less template in the sequencing reaction, especially if you use the BigDye® XTerminator™ Purification Kit (see Table 8, “Recommended DNA template quantities for cycle sequencing,” on page 63).
Electrophoresis issue: Modified run module with increased injection time was used.	Use an unmodified standard run module.

Double peaks: at the beginning of the sequence




See also [page 224](#) for the raw data view

Double peaks at the beginning of the sequence

Single peaks for the remaining sequence


Possible Cause(s)	Recommended Action
Sequencing reaction issue: Observed when a PCR product is used as a sequencing template. Caused by the formation of primer-dimers during the PCR reaction. The primer-dimers anneal and are filled in to create short, non-template PCR products.	If the sequence within the region affected by the primer-dimer sequence is important, either: <ul style="list-style-type: none"> • Redesign the PCR primers to eliminate the sequences that allow primer-dimer formation or • Use a “hot start” PCR enzyme to inhibit primer-dimer formation
More than 1 PCR product is present in the PCR reaction.	Re-examine the sequence for primer site homology. Redesign as necessary
More than 1 priming site (either upstream or downstream) on the sequencing template.	

Double peaks: at the beginning of the sequence (bisulfite conversion)




Possible Cause(s)	Recommended Action
Sequencing reaction issue: Observed when a PCR product is used as a sequencing template. Caused by the formation of primer-dimers during the PCR reaction. The primer-dimers anneal and are filled in to create short, non-template PCR products.	If the sequence within the region affected by the primer-dimer sequence is important, use M13 tails with both forward and reverse primers and either: <ul style="list-style-type: none"> Redesign the PCR primers to eliminate the sequences that allow primer-dimer formation or Use a “hot start” PCR enzyme to inhibit primer-dimer formation

Double peaks: specific peaks under specific bases




Possible Cause(s)	Recommended Action
Electrophoresis issues:	
Poor or incorrect instrument spectral calibration. Inspection of the raw data shows all secondary peaks directly under primary peaks.	Perform a new spectral calibration run. Follow the procedures in your instrument user guide. Then run your samples again.
Poor quality matrix (310 instruments only).	Create a new matrix file.
Sequencing reaction issue: Signals of the sample exceed the range used for spectral calibration because too much template was used.	Click the Annotation tab and examine the Ave Signal Intensity. Excessive signal: <ul style="list-style-type: none"> • 3730/3730xl instruments: >10,000 rfus • 310 and 31XX instruments: >1000 rfus Load less labeled sample by performing one of the following: <ul style="list-style-type: none"> • Dilute the resuspended product with Hi-Di™ Formamide before loading onto the instrument • Inject sample for less time • Resequence the samples, using less template in the sequencing reaction, especially if you use the BigDye® XTerminator™ Purification Kit (see Table 8, “Recommended DNA template quantities for cycle sequencing,” on page 63).

Double peaks: specific peaks under specific bases




Possible Cause(s)	Recommended Action
Data analysis issue: Using the ABI basecaller when analyzing sequences for bisulfite-treated DNA. Bisulfite treatment of DNA for methylation studies should convert all unmethylated Cs to uracil, so the sequence should contain very few C peaks. However, during sequence analysis, the analysis software overcalibrates for the absence of C peaks.	Use the KB basecaller to analyze sequences for bisulfite-treated DNA.

Double peaks: peaks under peaks throughout (bisulfite conversion)




Possible Cause(s)	Recommended Action
<p>Sequencing reaction issue: Incomplete bisulfite conversion, indicated by the presence of Cs (blue) not adjacent to Gs (black). A C at a non-CpG position serves as an internal control for complete bisulfite conversion.</p> <p>Incomplete bisulfite conversion may be due to:</p> <ul style="list-style-type: none"> • Impure gDNA • Too much gDNA • Inadequate denaturation of gDNA prior to bisulfite conversion 	<ol style="list-style-type: none"> 1. Check DNA quantitation and quality (page 44 and 45). 2. Repeat the bisulfite conversion 3. Repeat the sequencing.

Double peaks: double sequence (n+1 or n-1) throughout




Possible Cause(s)	Recommended Action
Sequencing reaction issues:	
Contamination of the PCR primer with n+1 or n-1 primer.	Use the primers with a different template. If the problem persists, resynthesize the primers before repeating the experiment.
Contamination of the sequencing primer with n+1 or n-1 sequencing primer.	
Sequencing primer contains a run of identical nucleotides, especially 4 or more Gs.	Design new sequencing primers, avoiding runs of identical nucleotides, especially 4 or more Gs.
Homopolymer at the beginning of the sequence.	See page 246 .

Double peaks: after a homopolymer or repeated sequence




Possible Cause(s)	Recommended Action
<p>Sequencing reaction issue: Stutter during either PCR amplification and/or cycle sequencing. Stutter is most common in any homopolymeric region greater than 2 bases. It can also be seen with simple repeated DNA sequences. The results are worse when the stutter occurs during PCR amplification.</p> <p>It is thought that stutter occurs when a partially extended primer and template dissociate, then reanneal improperly before extension continues. Partially extended primers and templates commonly dissociate during the reaction, but if they reanneal with complete fidelity, the reaction produces only one product. Improper annealing results in one or more products that are represented in the sequencing results.</p>	<p>If stutter occurs during PCR amplification, little can be done to correct the problem, except using anchored sequencing primers.</p> <p>If stutter occurs during cycle sequencing:</p> <ul style="list-style-type: none"> • Try using dRhodamine terminators. They have been shown to be less prone to produce stutters, specifically with poly-T regions. • Some customers have found that they can get past poly(A) regions using a mixture of oligo dT₁₈ primers with either a C, A, or G as the 3' terminal dinucleotide or 2-base anchors.

Double peaks: after a homopolymer or repeated sequence (bisulfite sequencing)




Possible Cause(s)	Recommended Action
<p>Sequencing reaction issue: Stutter during either PCR amplification and/or cycle sequencing. Stutter is most common in any homopolymeric region greater than 2 bases. It can also be seen with simple repeated DNA sequences. The results are worse when the stutter occurs during PCR amplification.</p> <p>It is thought that stutter occurs when a partially extended primer and template dissociate, then reanneal improperly before extension continues. Partially extended primers and templates commonly dissociate during the reaction, but if they reanneal with complete fidelity, the reaction produces only one product. Improper annealing results in one or more products that are each represented in the sequencing results.</p>	<p>If stutter occurs during PCR amplification, little can be done to correct the problem, except using anchored sequencing primers.</p> <p>If stutter occurs during cycle sequencing:</p> <ul style="list-style-type: none"> • Try using dRhodamine terminators. They have been shown to be less prone to produce stutters, specifically with poly(T) regions. • Some customers have found that they can get past poly(A) regions using a mixture of oligo dT₁₈ primers with either a C, A, or G as the 3' terminal dinucleotide or 2-base anchors. • Avoid stretches with > 8 As or Ts. • Use BigDye® Terminator Ready Reaction Mix at full strength. • Use AmpliTaq Gold polymerase.

Double peaks: double sequence after clean sequence




Possible Cause(s)	Recommended Action
Heterozygous indel mutation (HIM).	<p>Obtain forward and reverse sequence data and assemble using SeqScape or Variant Reporter™ Software.</p> <ul style="list-style-type: none">SeqScape Software lists HIMs in the Mutations Report. Review the mutation by clicking the Base Change in the Mutations Report to view the mutation in the Project view.Variant Reporter Software lists HIMs in the Project Summary Report.

Resolution loss: at beginning of run



Possible Cause(s)	Recommended Action
Sequencing reaction issues:	
XTerminator™ Solution or premix exposed to temperature over 25 °C.	<ul style="list-style-type: none"> • Use appropriate adapter for vortexer • Make sure plate does not heat up during vortexing step
BigDye XTerminator Purification Kit reagents past their expiration date.	<ul style="list-style-type: none"> • Verify expiration dates on reagents and discard if expired • Store XTerminator Solution at 4 °C • Store SAM Solution at room temperature


Resolution loss: in the middle of the run



Loss of peak resolution in the middle of the run

Possible Cause(s)	Recommended Action
Electrophoresis issues:	
Migration of a contaminant or microbubbles through the capillary during electrophoresis.	Run the sample again.
Syringes, polymer block, or septa contaminated with chemicals during cleaning.	<ol style="list-style-type: none"> 1. Perform a water wash through the polymer delivery system, using the Data Collection Software wizard. 2. Replace polymer, buffer, and water/waste with fresh materials. 3. Run the sample again.
Incomplete replacement of polymer between runs.	Check the polymer delivery system for leaks, looking for residue in and around the polymer block area; check the pin valve for signs of arcing on the tip; check for polymer in the anode buffer jar. If you see evidence of a leak, retighten, then run the sample again. If the leaking persists, contact Applied Biosystems to arrange a service engineer visit.


Resolution loss: gradual early loss



Possible Cause(s)	Recommended Action
Electrophoresis issues:	
Capillary array degrading.	<ol style="list-style-type: none"> 1. Perform a water wash through the polymer delivery system, using the Data Collection Software wizard. 2. Replace the capillary/array. 3. Run a sequencing standard. 4. If the problem persists, replace reagents, then run your samples again.
Samples degraded because they sat in the instrument too long, >48 hours.	Prepare additional sample for electrophoresis, referring to “Minimum Sample Volume” on page 122 . Then, run the samples again.
Expired or old reagents: polymer, Hi-Di™ Formamide, buffer, or water.	Replace the reagent, then run your samples again.

Possible Cause(s)	Recommended Action
Electrophoresis source is faulty, resulting in unstable current.	Contact Applied Biosystems to arrange a service engineer visit.
Extension products purified using bead-based kits were injected without removing the magnetic beads. The beads may interfere with the extension products during injection and cause overloading or other injection anomalies.	Remove magnetic beads before loading the sample.
Capillaries overloaded with sequencing product.	<p>Click the Annotation tab and examine the Ave Signal Intensity. Excessive signal:</p> <ul style="list-style-type: none"> • 3730/3730xl instruments: >10,000 rfus • 310 and 31XX instruments: >1000 rfus <p>Load less labeled sample by performing one of the following:</p> <ul style="list-style-type: none"> • Dilute the resuspended product with Hi-Di Formamide before loading onto the instrument • Inject sample for less time • Resequence the samples, using less template in the sequencing reaction (especially if you use the BigDye® XTerminator™ Purification Kit) (see Table 8, "Recommended DNA template quantities for cycle sequencing," on page 63).
Blending Ready Reaction Mixes from dGTP BigDye terminator kits with BigDye terminator vx.1 kits.	Do not use blended Ready Reaction Mixes of dGTP BigDye Terminator kits and BigDye Terminator vx.1 kits in these cases.
Use of non-Applied Biosystems reagents.	<ol style="list-style-type: none"> 1. Perform a water wash on all components of the system using the wizard in Data Collection Software. 2. Replace reagents with Applied Biosystems products. <p>Note: the performance of non-Applied Biosystems reagents cannot be guaranteed.</p>

High quality sequence in unassembled category in SeqScape Software



Possible Cause(s)	Recommended Action
SeqScape or Variant Reporter™ Software detects no similarity between the sample sequence and the reference sequence. The gray sequence indicates that the trimming of the data to the reference sequence failed.	Make sure that the sample is included in the right project.
Incorrect sample identification when a sample belonging to another project was imported.	

Troubleshooting Index

A

- annotation tab, reviewing [195](#)
- artifacts, reviewing for [194](#)
- average signal intensity
 - high values [204](#), [212](#), [223](#), [237](#), [240](#), [250](#)
 - low value for C [229](#)
 - reviewing [195](#)

B

- base spacing
 - reviewing [195](#)
- basecaller
 - appropriate location for file [193](#)
 - verifying correct one is used [193](#)
- basecalling
 - mixed bases not called correctly [202](#)
 - stops [217](#)
 - too many mixed bases called [203](#)
- baseline
 - negative [214](#), [215](#)
 - reviewing [194](#)
 - waterfall symptom [216](#)
- BDX Update utility [208](#)
- BigDye® terminators
 - irregular C peaks symptom [229](#)
 - irregular G peaks symptom [231](#)
- BigDye® XTerminator™ Purification Kit
 - BDX Update utility [208](#)
 - symptom of incorrect run module [223](#)
- bisulfite sequencing
 - broad peaks [234](#)
 - double peaks after homopolymer [245](#)
 - double peaks at the beginning [239](#)
 - peaks under peaks throughout [242](#)
- blobs in electropherogram [228](#)

C

- C peaks, irregular [229](#)
- compressions, of peaks [233](#)
- controls
 - troubleshooting using [192](#)
- current during run, reviewing [196](#)

D

- data analysis
 - PCR stop point [217](#)
 - reviewing information [194](#)
 - reviewing settings [193](#)
 - settings on annotation tab [195](#)
 - when mobility file is incorrect [227](#)
 - with incorrect mixed bases settings [202](#)
 - with incorrect quality threshold setting [202](#)
- Data Collection Software
 - settings on Annotation tab [195](#)
- data start point, reviewing [194](#)
- dGTP BigDye® terminators
 - peak compression symptom [233](#)
- DNA quality
 - troubleshooting [197](#)
- DNA quantity
 - troubleshooting [197](#)
- DNA template
 - difficult to sequence [218](#)
- double peaks
 - after homopolymer or repeated sequence [244](#), [245](#)
 - double sequence after clean sequence [246](#)
 - n+1 or n-1 sequence throughout [242](#)
 - peaks under peaks throughout [235](#)
 - specific peaks under specific bases [240](#), [241](#)
 - with high average signal intensity values [237](#)
- dye degradation
 - symptom of [229](#), [231](#), [232](#)

E

- electropherogram
 - example [193](#)
 - reviewing [193](#)
- EPT tab, reviewing [196](#)
- examples
 - electropherogram [193](#)
 - EPT tab [196](#)
 - raw data [194](#)
 - troubleshooting symptoms [199](#)

G

- G peaks, irregular [231](#)

H

heterozygous indel mutation (HIM) detection 246
homopolymeric regions
troubleshooting sequencing of 204, 232, 236, 244, 245

I

indel, detection of 246
instrument run
reviewing 194

M

M13mp18 control
troubleshooting using 192
matrix file
appropriate location for 193
verifying correct one used 193
mixed bases
not called correctly 202
too many called 203
mobility file
appropriate location for 193
verifying correct one used 193

N

n+1 or n-1 sequence throughout 242

P

PCR stop point 217
peak heights, reviewing in raw data 194
peak symptoms
blobs 228
compressed peaks 233
double peaks 237, 238, 240, 241, 242, 244, 246
irregular C peaks 229
irregular G peaks 231
large peaks 228
missing C peaks 229
n+1 or n-1 sequence throughout 242
peaks under peaks throughout 235
resolution loss 248, 249
shoulders 229, 232
spikes 224, 225
split peaks 223
unevenly spaced peaks 227
pGEM-3Zf(+) control
troubleshooting using 192
poly(A) regions, sequencing 245
poly(T) regions, sequencing 245
polymer
problems caused by crystals 224
problems caused by heating 224, 225

power during run, reviewing 196

primers

primer-dimer formation 222
reviewing design of 198

R

raw data
example of high quality 194
reviewing 194
read length, reviewing 194
Ready Reaction Mix
blended 232, 250
improper storage 206
insufficient quantity 205, 209, 218, 219, 220, 221
reptation peak 226
resolution
loss of 212, 248, 249
run. See instrument run.

S

Sample Manager
example 193
red spacing value in 201
SeqScape® Software
detection of HIM using 246
high quality sequence in unassembled category
symptom 251
Sequencing Analysis Software
red spacing value in 201
reviewing data analysis settings 193
reviewing run and analysis information 194
sequencing standards
troubleshooting using 192
shoulders
on all peaks 232
on C peaks 229
signal symptoms
excessive signal 223
low signal 205, 207, 209
negative baseline 214, 215
no signal 205, 207
signal starts later than expected 211, 212
ski slope profile 221
spike 224, 225, 226
sudden drop in signal 217, 218, 219
top-heavy data 220, 221, 222, 223
waterfall baseline 216
signal/noise
reviewing 195
ski slope profile 221
spacing of peaks, troubleshooting 227
spacing value, red 201
spectral pull-up 235
spikes

- at end of run 226
- four-color 224
- one-color 225
- split peaks 223
- stutter 204, 232, 236, 244, 245
- symptoms
 - blobs in electropherogram 228
 - double peaks 235, 237, 238, 240, 241, 242, 244, 246
 - excessive signal 223
 - high quality sequence in unassembled category 251
 - irregular C peaks 229
 - irregular G peaks 231
 - large peaks 228
 - low signal 205, 207, 209
 - missing C peaks 229
 - mixed bases not called correctly 202
 - n+1 or n-1 sequence throughout 243
 - negative baseline 214, 215
 - no signal 205, 207
 - peak compressions 233
 - peak shoulders 232
 - peaks under specific bases 240, 241
 - peaks unevenly spaced 227
 - resolution loss 212, 248, 249
 - shoulders on peaks 229
 - signal drops suddenly 217, 218, 219
 - signal starts later than expected 211, 212
 - ski slope profile 221
 - spikes 224, 225, 226
 - split peaks 223
 - table of 199
 - too many mixed bases called 203
 - top-heavy data 220, 221, 222, 223
 - waterfall baseline 216
- troubleshooting 192

T

- temperature of run
 - reviewing 196
- top-heavy data 220, 221, 222, 223
- troubleshooting
 - DNA quantity and quality, reviewing 197
 - EPT tab 196
 - overview 192
 - primer design, reviewing 198
 - symptoms table 199
 - workflow 192

V

- voltage
 - reviewing 196

W

- waterfall baseline 216
- workflows